

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

402

PRODUCT AFFECTED


OB-8

DRAWINGS AFFECTED


SCHEMATIC 1679A SHEET 2

DESCRIPTION OF CHANGE

OLD:



NEW:



ADD .022mf CAPACITOR IN
PARALLEL WITH R29.

REASON FOR CHANGE

TO ELIMINATE NOISE WHEN CONTROLLING THE VOLUME WITH
AN EXTERNAL LOW IMPEDANCE VOLTAGE SOURCE.

(FOR EXAMPLE, A CV OUTPUT OF THE DSX PLUGGED INTO THE VOLUME FOOT PEDAL INPUT)

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☒ RETROFIT IF NEEDED IN FIELD

WRITTEN BY

DATE

MICHEL

12/9/82

APPROVED BY

DATE

[Signature]

12/9/82

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.
403

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

1682 SHEET 2 of 3

DESCRIPTION OF CHANGE

REVERSE POSITION OF R101 & R101 ON drawing
" " " D201 & R201 " "
" " " D301 & R301 " "
" " " D401 & R401 " "

C32 connected to pin 5 of U35 should be C34

C23 connected to pins of U21 should be C3

ADD R32 to 100K 1% connected to pin 2 of U33

ADD R33 to 4.87K 1% connected to pin 2 & pin 1 of U33

CHANGE R33 (560R) to R35 sheet 1 of 3

ADD R36 to 47K connected to pin 4 of U26

CHANGE pin 4 (output control) U13 to pin 1

REASON FOR CHANGE

To match schematic to board layout.

EFFECTIVITY

- ☐ FUTURE PRODUCTION ONLY
☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
☐ RETROFIT UNITS IN FIELD
☒ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED

WRITTEN BY

DATE

PL

7dec82

APPROVED BY

DATE

290

12-7-82

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.
404

PRODUCT AFFECTED


OB-8

DRAWINGS AFFECTED

OB-8 POT. Board 1&2 1681A

DESCRIPTION OF CHANGE

Reduce output of 5.6v Supply.



REASON FOR CHANGE

Increase the active range of the Front panel pots

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐

WRITTEN BY

DATE

PETER MURSON 12/10/82

APPROVED BY

DATE

[Signature] 12/10/82

* REVISED 1-5-83 *

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

406

PRODUCT AFFECTED

OB-8


DRAWINGS AFFECTED

OB-8 VOICE BOARD 1682 A

DESCRIPTION OF CHANGE

Add a resistor between -5v and pin 2 of U33 (upper & lower voice)
A software revision A-4 or posterior must be installed and the offset
calibration of the service center test must be performed.

ADDED



REASON FOR CHANGE

The offset calibration routine of the service center test can correct
the TL084 for positive or negative offset.

EFFECTIVITY

- ☐ FUTURE PRODUCTION ONLY
- ☒ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

MICHEL DODIC

12/12/82

APPROVED BY

DATE

[Signature]

12/12/82

PRODUCT AFFECTED

08-8



DRAWINGS AFFECTED

SCHEMATIC 1679 A, SHEET 2
08-8 PROCESSOR BOARD

DESCRIPTION OF CHANGE

OLD:

NEW:



ADD PNP TRANSISTOR, 47K AND 1K RESISTORS

REASON FOR CHANGE

TO REDUCE POWER-DOWN GLITCH AT OUTPUTS

ACTIVITY

- ☐ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☒ RETROFIT AS NEEDED

WRITTEN BY

DATE

Randy Evans

12-15-82

APPROVED BY

DATE

[Signature]



12-15-82

OR-8

NONE

DESCRIPTION OF CHANGE

OLD:



NEW

ADD A 100pF CAPACITOR
IN PARALLEL WITH R34

REASON FOR CHANGE

REASON FOR CHANGE
ON REVISION A PROCESSOR BOARDS, WHEN A SEQUENCER IS CONNECTED,
DISTORTION BECOMES PRESENT IN THE NOISE GENERATOR.

EFFECTIVITY

- ☐ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☒ RETROFIT REV. "A" BOARDS ONLY

WRITTEN BY

DATE _____

12/24

APPROVED BY

DATE _____

42 12/22/82

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

409

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

1682A

DESCRIPTION OF CHANGE

ADD A 33K RESISTOR ON EACH VOICE (2 PLACES)
TO RX27. THIS RESISTOR WAS 4.7K BUT WAS REMOVED
BY ECO 405.

REASON FOR CHANGE

TO KEEP OSC 2 FROM GOING SHARP WHEN
THE SAWTOOTH WAVE IS SELECTED.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY


DATE

RANDY EVANS

12/22/82

APPROVED BY

DATE



12/22/82

* REVISED 1-5-83 *

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

410

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

NONE

DESCRIPTION OF CHANGE

REMOVE EPROMS A30-A33 FROM SOCKETS
U21 THROUGH U24, AND REPLACE WITH NEW
SOFTWARE, EPROMS A40-A43.

- ECO'S 405, 406, 409 must be implemented. -

REASON FOR CHANGE

TO ADD THE OUTPUT 3080 (U503) OFFSET
CALIBRATION PROCEDURE TO THE TEST SOFTWARE

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
☐ RETROFIT UNITS IN FIELD
☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
☐ _____

WRITTEN BY

DATE

MICHEL DOIDIC 12/22/81

APPROVED BY

DATE

Dco 12/22/82


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

OB-8 BEND BOX 1680A SHEET 1 OF 1

DESCRIPTION OF CHANGE



REASON FOR CHANGE

- REMOVES NOISE MODULATION FROM BENDER LEVER

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

MICHEL DODIC

1/6/83

APPROVED BY

DATE

[Signature] 1/6/83


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

PROCESSOR BOARD- POWER SUPPLY
1679A SHEET 4 of 4

DESCRIPTION OF CHANGE



(REFERENCE ECO #401)

REASON FOR CHANGE

WHEN THE NEW POWER SUPPLY TRANSFORMER (REF.561021) IS USED, THIS CHANGE DECREASES THE OUTPUT THUMP ON POWER OFF.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

MICHEL DOLIC

DATE

1/18/83

APPROVED BY

[Signature]

DATE

1/18/83

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

413


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

VOICE BOARD 1682A SHEET 2 OF 3

DESCRIPTION OF CHANGE



REASON FOR CHANGE

REMOVE LEAK OF NOISE GENERATOR WHEN A VOICE IS GATED

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

MICHEL DODIC

DATE

1/18/93

APPROVED BY

DATE

[Signature]

1/18/93

PRODUCT AFFECTED



OB-8

DRAWINGS AFFECTED

1682A VOICE BOARD

2 POLE/4 POLE CONFIGURATION

DESCRIPTION OF CHANGE



REASON FOR CHANGE

RESISTOR AT UX06 PINS 10, 18 MARKED RX68 SHOULD BE RX61.

CAPACITOR IN 2 POLE/4 POLE CONFIGURATION DRAWING MARKED C20 SHOULD BE C14.

EFFECTIVITY

- ☐ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☒ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

PAUL WHITE 1/20/83

DATE

APPROVED BY

1/20/83

DATE

OBERHEIM ELECTRONICS, INC.

ECO NO.

ENGINEERING CHANGE ORDER

415

PRODUCT AFFECTED


OB-8

DRAWINGS AFFECTED

SCHEMATIC

1682 B OB-8 VOICE BOARD (UPPER)

DESCRIPTION OF CHANGE



Change C508 from 0.1 μ f Mylar To 2.2 Electrolytic (Upper Voice only)

REASON FOR CHANGE

To eliminate noise at output at low master volume levels

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

Randy Evans

1-26-83

APPROVED BY

DATE

1-27-83



DUCT AFFECTED

OB-8

DRAWINGS AFFECTED

1632 B OB-8 Voice Board
1689 B

DESCRIPTION OF CHANGE



Add a .022 Mylar Capacitor To both The Top and bottom Voice Boards

REASON FOR CHANGE

To Filter-OUT digital noise picked up along The Filter Pedal line (VCFF)
when a Sequencer (DSX) is connected.

ACTIVITY

FUTURE PRODUCTION ONLY

RETROFIT UNITS IN PRODUCTION AND INVENTORY

RETROFIT UNITS IN FIELD

DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED

As Required in Test

WRITTEN BY

Randy Evans

APPROVED BY

[Signature]

DATE

2-3-83

DATE

2-3-83


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

OB-8 VOICE BOARD 1632 B SHEET 3 of 3

DESCRIPTION OF CHANGE



— ALSO: UX08 IS DELETED AND REPLACED BY THE OTHER CELL OF THE 74182 UX14

REASON FOR CHANGE

— RATIONALIZE THE CIRCUITRY

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY, START WITH VOICE BOARD PC 658B
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐

WRITTEN BY

MICHAEL DOOLEY

DATE

2/1/83

APPROVED BY

2/1/83

DATE

2/1/83

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

- 5

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

OB-8 VOICE BOARD 1682B SHEET 3 OF 3

DESCRIPTION OF CHANGE

RX'D ON VCO1 AND RX23 ON VCO2 BECOME $\pm 2 \leq 1\%$

REASON FOR CHANGE

- BRING THE TRACKING TRIMMER IN THE MIDDLE

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY, START WITH VOICE BOARD PC 652B
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

MICHEL DOLDIC

2/1/82

APPROVED BY

DATE

ASO

2/15/83

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

420

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

VOICE BOARD 1682B SHEET 1,2,3

DESCRIPTION OF CHANGE

THE VOICE BOARD PRINTED CIRCUIT 1658A IS REPLACED BY
PRINTED CIRCUIT 1658B

ECOs 413 417 418 419 ARE IMPLEMENTED

REASON FOR CHANGE

- REMOVES CUTS AND JUMPERS

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
☐ RETROFIT UNITS IN FIELD
☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
☐ _____


WRITTEN BY

DATE

MICHEL DODIC 2/11/93

APPROVED BY

DATE

 2/15 93

DUCT AFFECTED


OB-8

DRAWINGS AFFECTED

POT BOARD

1681 B

DESCRIPTION OF CHANGE



ASON FOR CHANGE

TO CENTER OSC 2 DETUNE CONTROL WHEN LED GOES OFF
WITH KNOB SIGNIFICANTLY COUNTERCLOCKWISE OF CENTER.

EFFECTIVITY

WRITTEN BY

DATE

☐ FUTURE PRODUCTION ONLY

BILL CANTHORNE

2-22-83

☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY

☐ RETROFIT UNITS IN FIELD

APPROVED BY

DATE

☒ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED

☒ AS REQUIRED

 2-24-83

CHANGED BY ECO # 433

OKERHEIM ELECTRONICS, INC.

ENGINEERING CHANGE ORDER

ECO NO.

422


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

OB-8 VOICE BOARD 1682B SHEET 2

DESCRIPTION OF CHANGE



R32 100K 1% are 50 Ω matched between Lower and upper Tray.

R32 on the Lower and upper tray are mounted after the two boards are screwed together.

REASON FOR CHANGE

—IMPROVES MATCHING OF TIMING BETWEEN ENVELOPES OF UPPER AND LOWER TRAY.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

MICHEL DODIC

DATE

3/10/83

APPROVED BY

[Signature]

DATE

3/10/83

PRODUCT AFFECTED

OB-8


DRAWINGS AFFECTED

1679 B - SHEET 1




1679 E - SHEET 4

DESCRIPTION OF CHANGE

WAS



SHOULD BE



REASON FOR CHANGE

IMPROVE MARGIN OF "PVP" CIRCUIT TO INADVERTENT TURN-OFF, ESPECIALLY AT 50 Hz.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☒ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☒ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐

WRITTEN BY

DATE

DEO

3-28-93

APPROVED BY

DATE

DEO

3-28-93

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

424

PRODUCT AFFECTED


OB-8

DRAWINGS AFFECTED

PROCESSOR BOARD 1679B SHEET 1 OF 4

DESCRIPTION OF CHANGE

THE Z80 RESET IS NOW DRIVEN BY
THE PUP SIGNAL -



REASON FOR CHANGE

TO AVOID POSSIBLE MEMORY DROP CAUSED BY SHORT POWER DROP

EFFECTIVITY

- ☐ FUTURE PRODUCTION ONLY
- ☒ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐

WRITTEN BY

DATE

NICHEL DOLDIC

4/11/93

APPROVED BY

DATE

[Signature]

4/11/93

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

425

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

NONE

DESCRIPTION OF CHANGE

REMOVE EPROMS A5-0, A5-1, A5-2, A5-3 FROM
SOCKET U21 THROUGH U24, AND REPLACE WITH NEW
SOFTWARE EPROMS A6-0, A6-1, A6-2, A6-3

REASON FOR CHANGE

The version A6 adds two new features to the version A5:

----- A) Every time a cassette is recorded from an OB-8, the envelope offset values of this very machine are stored at the end of the patch transfer.

When this cassette is played back the envelope offset values may be retrieved from the cassette. To do so, you must hold down simultaneously the six following switches and then push PLAY.

OSC1 ON, OSC2 HALF, OSC2 FULL, NOISE, 4 POLE, TRACE

This feature lets you save the envelope offset data before you change the battery or a memory chip and in a more general way, enables you to send to service an OB-8. It also gives to the user the possibility of restoring the envelope offset value after an unfortunate memory drop.

----- B) The program data may be reinitialized like at the first power on. To do so, the memory protect switch must be off and you must hold down simultaneously the program 1 to 8 switches and then push SPLIT (see your ribbon ...).

This procedure is useful if you cannot retrieve the envelope offset data from a cassette after another unfortunate memory drop. The reinitialization will set the offsets to their mid value and the envelope will be playable even if they are not well matched.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
☐ RETROFIT UNITS IN FIELD
☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
☐ _____

WRITTEN BY

DATE

MICHEL DO.DIC

4/11/83

APPROVED BY

DATE

Deo

4/11/83

PRODUCT AFFECTED


OB-8

DRAWINGS AFFECTED

POWER SUPPLY

DESCRIPTION OF CHANGE

ADD A JUMPER BETWEEN PIN 1 OF THE -15 REGULATOR
7915 (GND) AND THE GROUND REFERENCE TEST POINT.
THE JUMPER MUST BE MADE OF A 18 AWG WIRE (.04 inch / 1 mm)
MINIMUM AND MUST BE SHORT.



REASON FOR CHANGE

TO REMOVE AC HUM ON AUDIO OUTPUT.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

MICHEL DODIC

7/11/83

APPROVED BY

DATE

[Signature]

4 .83

PRODUCT AFFECTED

00-8

DRAWINGS AFFECTED

00-8 SERVICE MANUAL

DESCRIPTION OF CHANGE

- SERVICE SOFTWARE ONLY -

SOFTWARE REVISION A7 : USE EPROMS A7-0, A7-1, A7-2, A7-3

CHANGE PROCEDURE OF OFFSET CALIBRATION AS FOLLOWS

THE FIRST 6 PARAMETERS (FILTER RLS, VCA RLS, FILTER DCY, VCA DCY, FILTER ATTACK, AND VCA ATTACK) ARE TO BE CALIBRATED FOR THEIR MAXIMUM VALUE (-2560V) INSTEAD OF THEIR MINIMUM (0.0V).

2. ACTIVATE CONTINUOUS RAM TEST BY PRESSING "LINE1" SWITCH. LOOK AT THE LEOS ON THE PROGRAM SECTION. NO LIGHTS MEANS ALL ARE FINE. FAILURE IN RAM0 (U10) IS INDICATED BY "A" BEING LIT, RAM1 (U19) = "B" ON AND IF "C" IS ON, THERE IS A FAILURE IN RAM2 (U18). ENTIRE CYCLE TAKES LESS THAN 1 S. THIS TEST RUNS CONTINUOUSLY UNTIL A NEW TEST IS SELECTED AND ONLY AN I.D. FAILS THE LED STAYS ON UNTIL THE TEST IS RESELECTED. OF COURSE, MEMORY PROTECT MUST BE OFF!

3. DURING LED TEST MODE, THE VOLUME IS TURNED ON, AND THE POTS MAY BE EASILY CHECKED FOR DEAD ZONES. THE FREQUENCY OF THE OSC. IS DETERMINED BY POSITION OF THE "LAST EDITED" POT. CONTROL JUMPS TO POT THAT IS BEING MOVED AND STAYS THERE UNTIL A NEW POT IS MOVED, BEND BOX RATE POTS ARE INCLUDED.

REASON FOR CHANGE

IMPLEMENT TWO NEW TESTS, AND IMPROVE OFFSET CAL.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY AND AS NEEDED.
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

ANNE GRAHAM 5/9/83

APPROVED BY

ACQ 5/13/83

OBERHEIM ELECTRONICS, INC.

ECO NO.

ENGINEERING CHANGE ORDER

428

PRODUCT AFFECTED

18-B

DRAWINGS AFFECTED

VOICE SCHEMATIC 1632B

BILL OF MATERIALS 723073-000

DESCRIPTION OF CHANGE

COMPONENT NO'S CX25 AND CX27

ON THE OB-B VOICE BOARDS, ENVELOPE SECTION, 16 PIECES PER DE-S:

WAS: PART NO. 153008 .047 μ F \pm 20% CAPACITOR.IS NOW: PART NO. 153021 .047 μ F \pm 5% CAPACITOR.

REASON FOR CHANGE

TIGHTEN TOLERANCE ON ENVELOPE SPEED CAPACITOR.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

ANNE GRAHAM

5-23-93

APPROVED BY

DATE

 5-23-93

PRODUCT AFFECTED




OB-8

DRAWINGS AFFECTED

OB-8 PROCESSOR BOARD 1679B sheet 1 of 4

DESCRIPTION OF CHANGE

NEW PUP CIRCUITRY:



- Remove D5, C30, R31 (Darkened components)
- Cut between Q3 base and R33
- Remove diode added by ECO 423 (under the board)
- Replace R53 with a 100K and R54 with a 47K

- Add a jumper between +5 and R53
- Add From under the board's 2 caps and 3 diodes

- Replace C1 (4700 μ F cap on 5v power supply) with a .0000 μ F .6v

REASON FOR CHANGE

- Avoid memory drop.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☒ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☒ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐

WRITTEN BY

MICHEL DOLDIC

DATE

5/21/83

APPROVED BY

DATE

6/21/83

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.
430

PRODUCT AFFECTED

OB-8 Voice upper/lower

DRAWINGS AFFECTED

1682 20F3
4
16828 20F3

DESCRIPTION OF CHANGE

U16,2 → R401 Should be U16,2 → R201
U16,6 → R201 Should be U16,6 → R401
also.

U15,6 → U16,5 Should be U15,6 → U16,1
U15,2 → U16,1 Should be U15,2 → U16,5

REASON FOR CHANGE

to correct OB-8 Voice Board Schematics

EFFECTIVITY

- ☐ FUTURE PRODUCTION ONLY
☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
☐ RETROFIT UNITS IN FIELD
☒ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
☐ _____

WRITTEN BY

f.m.

DATE

4-7-83

APPROVED BY

ACG

DATE

4-7-83

OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

431


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

ECO no 419

DESCRIPTION OF CHANGE



change value of -1 divider on each voice board

REASON FOR CHANGE

- ALLOWS USE OF SIGNETICS' 4016 &
IDENTIFIES COMPONENTS

EFFECTIVITY

WRITTEN BY

DATE



FUTURE PRODUCTION ONLY

MICHEL DODIC

6/27/83



RETROFIT UNITS IN PRODUCTION AND INVENTORY

APPROVED BY

DATE



RETROFIT UNITS IN FIELD



DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED

6-27-83



OBERHEIM ELECTRONICS, INC.
ENGINEERING CHANGE ORDER

ECO NO.

433

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

OB-8 VOICE BOARD 1682B sheet 2

DESCRIPTION OF CHANGE

ECO NO. 422 IS CANCELLED. R32 ON LOWER AND UPPER
VOICE BOARD ARE NOT MATCHED ANYMORE.

REASON FOR CHANGE

- THE NEW ENVELOPE CALIBRATION SOFTWARE STARTING WITH
A7 (SEE ECO 427) DOES NOT REQUIRE THOSE RESISTORS TO BE MATCHED

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
☐ RETROFIT UNITS IN FIELD
☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
☐

WRITTEN BY

DATE

MICHEL DOLDIC

7/5/83

APPROVED BY

DATE

A. G. C.

7/5/83

PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

NONE

DESCRIPTION OF CHANGE

- REPLACE EPROMS IN SOCKET U21 THROUGH U24 WITH NEW SOFTWARE EPROMS AB-0, AB-1, AB-2, AB-3

The software version AB contains the following new features:

- 1) -- LEGATO PORTAMENTO
- 2) -- EQUAL TIME LINEAR PORTAMENTO
- 3) -- EXPONENTIAL PORTAMENTO
- 4) -- INVERT LFO FREQUENCY MODULATION ON VCO 1
- 5) -- INVERT LFO PULSE WIDTH MODULATION ON VCO 1
- 6) -- VCF TRACKING OF THE BEND LEVER
- 7) -- REVERSABLE BEND LEVER
- 8) -- REVERSABLE MODULATION LEVER

- IF THE PREVIOUS SOFTWARE WAS A3 OR PREVIOUS; ECOs 405, 406, 408 MUST BE IMPLEMENTED AND THE OFFSET CALIBRATIONS MUST BE DONE AS DESCRIBED BY ECO 427
- IF THE PREVIOUS SOFTWARE WAS A4 THE OFFSET CALIBRATION MUST BE DONE AS DESCRIBED BY ECO 427

REASON FOR CHANGE

- ADD NEW FEATURES.

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐ _____

WRITTEN BY

DATE

MICHEL DODIC

7/12/83

APPROVED BY

DATE

DODIC

7/12/83

ENGINEERING CHANGE ORDER

PRODUCT AFFECTED:

OB-8

DRAWINGS AFFECTED: OB-8 VOICE
BOARD SCHEMATIC (No. 1682B)
AND PARTS LAYOUT (No. 1689B)

ECO NO.

435

EFFECTIVITY:

- ☐ AS REQUIRED IN TEST
☒ FUTURE PRODUCTION
☐ RETROFIT PRODUCTION & INVENTORY
☐ RETROFIT IN FIELD ☐ AS NEEDED
☐ DRAWING CORRECTION ONLY
☐

REASON FOR CHANGE:

REMOVE NOISE ON "VCFP"
(VCF PEDAL) LINE.

WRITTEN BY:

P. MUNSON

DATE:

10-13-83

APPROVED BY:

DEO

DATE:

10-17-83

DESCRIPTION OF CHANGE:

ECO 416 ("AS NEEDED") IS MADE A
PERMANENT CHANGE.

(ADD .022MF CAP BETWEEN "VCFP"
LINE AND GROUND).



© OBERHEIM ELECTRONICS, INC.

2250 South Barrington Avenue, Los Angeles, California 90064, (213) 473-6574

10. Turn the Interface board chip-side down with the ribbon cables sticking out to the left. The 16-pin ribbon will be above the 40-pin ribbon. Pin 1 of both ribbon cables is located at the tops of the sockets. Insert the 40-pin ribbon header into socket 26 on the processor board, being careful to line up pin-1 of cable with notch on socket.

11. Insert the 16-pin ribbon header into socket 41 on the processor board. When the header is properly installed, the cable will stick straight out from the right side of socket 41.

12. Position the four spacers over the four empty screw holes in the processor board. Turn the Interface board over and position the four holes in the corners over the spacers. Insert the long screws through the corner holes in the Interface board through the spacers and into the holes in the processor board.

13. The middle cable on the endbell assembly is "MIDI OUT". Connect this cable to the molex connector on the Interface board labeled "MIDI OUT". The rear cable on the endbell assembly is labeled "MIDI IN" and should be connected to the molex labeled "MIDI IN" on the interface board. "MIDI THRU" should be connected to "MIDI THRU".

14. To insure proper operation after changing the EPROMS, the RAM chips should be cleared. To do this carefully remove each RAM from it's socket and then carefully put it back in. Do this with all three RAM chips. They are I.C.'s 18, 19, and 20.

14. Close the front cover and replace the front cover screws.

15. Re-connect the AC power cord.

16. With the memory protect switch OFF (rear panel), turn the power on. Load the saved data from cassette, including the offsets. See page 43 of the OB-8 owners manual (included).

17. Press AUTOTUNE.

18. Apply sticker to the rear of the OB-8 above Computer Interface connector.

ENGINEERING CHANGE ORDER

PRODUCT AFFECTED:

OB-8

DRAWINGS AFFECTED:

1679 A sheet
4 of 4

ECO NO.

437

EFFECTIVITY:

- ☐ AS REQUIRED IN TEST
☐ FUTURE PRODUCTION
☐ RETROFIT PRODUCTION & INVENTORY
☐ RETROFIT IN FIELD ☐ AS NEEDED
☐ DRAWING CORRECTION ONLY
☐

REASON FOR CHANGE:

to stop loss of offsets in memory
on pur down. (like DSX)

WRITTEN BY:

Peter Manson

DATE:

6/15/84

APPROVED BY:

[Signature]

DATE:

6/15/84

DESCRIPTION OF CHANGE:

add. MOV 150v varistors to primary of X-former



OBERTHEIM ELECTRONICS, INC.

2250 South Barrington Avenue, Los Angeles, California 90064, 213-473-6574

ENGINEERING CHANGE ORDER

PRODUCT AFFECTED
08-8 ASSY#730114

DRAWINGS AFFECTED
08-8 MOD CAN SCHEMATIC
SHEET 1 OF 1.

ECO No
440

AFFECTIVITY.


- ☒ AS REQUIRED IN TEST
☒ FUTURE PRODUCTION
☐ RETROFIT PRODUCTION & INVENTORY
☒ RETROFIT IN FIELD ☒ AS NEEDED
☐ DRAWING CORRECTION ONLY
☐

REASON FOR CHANGE.

REMOVE NOISE MODULATION FROM
VIBRATO LEVER, AND CORRECT
SCHEMATIC.

WRITTEN BY:
PETE MUNSON



DATE:
9-7-84

APPROVED BY:


DATE:
9-7-84

DESCRIPTION OF CHANGE:

1. CHANGE SCHEMATIC AS SHOWN.
2. ADD .01uF CAP (OB.153004) FROM GROUND TO TEST POINT (T.P. 2) OF MOD CAN PCB ON 1666 SIDE OF BOARD.



OBERHEIM ELECTRONICS, INC.

2250 South Barrington Avenue, Los Angeles, California 90064. (213) 473-6574

ENGINEERING CHANGE ORDER

PRODUCT AFFECTED
OB-8 ASSY. #720073

DRAWINGS AFFECTED VOICE BOARD
SCHEMATIC 1682B SHEET 3 OF 3

ECO No

441

AFFECTIVITY:

- ☐ AS REQUIRED IN TEST
☒ FUTURE PRODUCTION
☐ RETROFIT PRODUCTION & INVENTORY
☐ RETROFIT IN FIELD ☐ AS NEEDED
☐ DRAWING CORRECTION ONLY
☐ _____

REASON FOR CHANGE

LOWER INITIAL FREQUENCY OF 3340
TO ACCOMMODATE A WIDER RANGE
OF CHARACTERISTIC VARIATIONS ON
THE 3340.

WRITTEN BY:
MICHEL DOJIC


DATE:
10-4-84

APPROVED BY:
[Signature]

DATE:
10-4-84

DESCRIPTION OF CHANGE:

REPLACE RESISTOR RX07 AND RX19 (215K, 1%)
WITH 174K, 1% (OB#475520).



OBERHEIM ELECTRONICS, INC.

2250 South Barrington Avenue, Los Angeles, California 90064, (213)473-6574


PRODUCT AFFECTED

OB-8

DRAWINGS AFFECTED

OB-8 VOICE BOARD 1682 A SHEET 30F2

DESCRIPTION OF CHANGE



REASON FOR CHANGE

- IMPROVES SYNCHRO SOUND

EFFECTIVITY

- ☒ FUTURE PRODUCTION ONLY, START WITH VOICE BOARD PC 1682 B
- ☐ RETROFIT UNITS IN PRODUCTION AND INVENTORY
- ☐ RETROFIT UNITS IN FIELD
- ☐ DRAWING CORRECTION ONLY; HARDWARE NOT AFFECTED
- ☐

WRITTEN BY

MICHEL DOLIC

DATE

2/11/83

APPROVED BY

DATE

2/15/83

The latest revision of software for the OB-8 contains several changes, designed to improve the OB-8's existing features as well as adding the following new features:

- 1) Legato Portamento
- 2) Equal Time Linear Portamento
- 3) Exponential Portamento
- 4) Inverted LFO Frequency Modulation on VCO1
- 5) Inverted LFO Pulse Width Modulation on VCO1
- 6) VCF Tracking of the Bend Lever
- 7) Reversible Bend Lever
- 8) Reversible Modulation Lever

NOTE: If the software to be replaced is "A3" or "A4", offset calibrations must be performed as described in ECO 427.

If the software to be replaced is "A1" or "A2", ECOs 405, 406, and 409 must be implemented and the offset calibrations must be performed as described in ECO 427.

INSTALLATION:

- 1) If the installation is done properly, the contents of the memory (RAM) will remain intact. However, storing the data on cassette will provide a backup if battery power to the Random Access Memory is accidentally interrupted.
- 2) Turn off power and disconnect the power cord from the OB-8.
- 3) Remove the two screws at the top of each endbell and lift up the front panel.
- 4) Remove the four EPROM memory chips (U21 through U24) labeled "A7-0", "A7-1", "A7-2", "A7-3". Earlier software revisions are labelled A6 or A5.
- 5) Install the four new EPROM memory chips. The chip labeled "A8-0" goes in location U24, "A8-1" goes in location U23, "A8-2" goes in location U22, and "A8-3" goes in location U21.

Make sure all of the chips have been installed correctly and that all of the pins have seated correctly in the sockets.

- 6) Close the unit and apply power. The OB-8 should return to the last selected program or to the cassette mode if the unit was last in cassette mode.